

SIMPLES T Y FORMAS EN U

Medidas Simples T		Sección en mm. h	Sección en mm. b	Sección en mm. e
	KG/M			
25	1,42	25	25	3,5
30	1,84	30	30	4,0
35	2,42	35	35	4,5
40	3,08	40	40	5,0
45	4,16	45	45	5,5
50	4,62	50	50	6,0
60	6,48	60	60	7,0
70	8,65	70	70	8,0
80	11,13	80	80	9,0
90	13,83	90	90	10,0
100	17,06	100	100	11,0

Medidas disponibles en
Granallado e Imprimado
a 12 metros

Medidas Ues		Sección en mm. h	Sección en mm. b	Sección en mm. e	Sección en mm. e1
	KG/M				
40 x 20	3,03	40	20	4,0	5,0
50 x 35	4,10	50	25	4,5	6,0
60 x 30	5,39	60	30	5,0	6,0